



# EMERSON ROAD INTERSECTION Milford, NH

## CLIENT

Town of Milford, NH

## LOCATION

Milford, NH

## PROJECT COMPLETION

2015

## DESCRIPTION

This project was needed as the Emerson Road Intersection was deficient; lacking dedicated turning lanes. This project brought the intersection up to current standards for improved mobility, safety and efficiency.

This intersection served several significant neighborhoods and an important recreational complex. Intersections, as opposed to highway segments, tend to be the limiting factor to the movement of goods and people. Without improvement, existing deficiencies at the intersection would persist and worsen as traffic and pedestrian volumes increased over time.

The intersection was currently signalized, but lacked the turn lanes to allow the traffic to move through the intersection. There were no existing pedestrian crossings, so the project added a short sidewalk segment and ADA compliant crossing to move pedestrians away from the intersection. Widening to accommodate these changes did not impact abutting properties.

In addition, the project has been designed to avoid an existing NHDOT culvert, avoiding additional wetlands permitting.

The project was constructed in a one-year time-frame.

- Intersection / Sidewalk Design
- LPA Program Coordination
- Construction Oversight
- Utility Coordination
- Permitting
- Contract Plans
- Environmental Documentation



Before



After